



Municipal Corporation, Gurugram

Fire Inspection Report : CFC Number 050261923004143



Building : AVL infra pvt Ltd
Reported by : ggnadfo@sr.com

Element	Thursday Oct,31 2019 2:17 PM	Lat = 28.41435618 Long = 76.98000644
Building		

Municipal Corporation, Gurugram

Fire Inspection Report : CFC Number 050261923004143

Building : AVL infra pvt Ltd
Reported by : ggnadfo@sr.com



Element	Thursday Oct,31 2019 2:17 PM	Lat = 28.41435618 Long = 76.98000644
Building		 <p>Narsinghpur नरसिंहपुर Sihi सीही SECTOR 83 गुर्गाँव Google</p> <p>→ OF</p> <p><i>Onup</i></p> <p>I.S. KASHYAP A.D.F.O.</p>

Municipal Corporation, Gurugram

Fire Inspection Report : CFC Number 050261923004143

Building :
Reported by :

AVL infra pvt Ltd
ggnadfo@sr.com



Element	Thursday Oct,31 2019 2:18 PM	Lat = 28.41435618 Long = 76.98000644
Building		

Municipal Corporation, Gurugram

Fire Inspection Report : CFC Number 050261923004143

Building :
Reported by :

AVL infra pvt Ltd
ggnadfo@sr.com



Element	Thursday Oct,31 2019 2:19 PM	Lat = 28.41435618 Long = 76.98000644
Building		 <p>Narsinghpur नरसिंहपुर</p> <p>Sihri सीहरी</p> <p>SECTOR 53 शेक्टर 53</p> <p>Google</p> <p>→ OH</p> <p><i>I.S. Kashyap</i></p> <p>I.S. KASHYAP A.D.F.O.</p>

Municipal Corporation, Gurugram

Fire Inspection Report : CFC Number 050261923004143

Building :
Reported by :



AVL infra pvt Ltd
ggnadfo@sr.com

Element	Thursday Oct,31 2019 2:19 PM	Lat = 28.41435618 Long = 76.98000644
Building		 <p>Narsinghpur नरसिंहपुर Sector 83 Phase B3 Google</p> <p>→ OI</p> <p><i>I.S. Kashyap</i> I.S. KASHYAP A.D.F.O.</p>

Municipal Corporation, Gurugram

Fire Inspection Report : CFC Number 050261923004143

Building : AVL infra pvt Ltd
Reported by : ggnadfo@sr.com



Element	Thursday Oct,31 2019 2:20 PM	Lat = 28.41435618 Long = 76.98000644
Building		

Municipal Corporation, Gurugram

Fire Inspection Report : CFC Number 050261923004143

Building :
Reported by :



AVL infra pvt Ltd
ggnadfo@sr.com

Element	Thursday Oct,31 2019 2:20 PM	Lat = 28.41435618 Long = 76.98000644
Building		

Municipal Corporation, Gurugram

Fire Inspection Report : CFC Number 050261923004143



Building : AVL infra pvt Ltd
Reported by : ggnadfo@sr.com

Element	Thursday Oct,31 2019 2:21 PM	Lat = 28.41435618 Long = 76.98000644
Building		 <p data-bbox="1118 1500 1449 1839">Narsinghpur नरसिंहपुर Sih सीही SECTOR 83 Area 83 Google → OL <i>I.S. Kashyap</i> I.S. KASHYAP A.D.F.O.</p>

Municipal Corporation, Gurugram

Fire Inspection Report : CFC Number 050261923004143



Building : AVL infra pvt Ltd
Reported by : ggnadfo@sr.com

Element	Thursday Oct,31 2019 2:22 PM	Lat = 28.41435618 Long = 76.98000644
Building	 A photograph showing the entrance of a white building. The ground in front of the entrance is covered with a large pile of broken bricks and debris. A person is visible near the glass entrance doors. The building has a balcony on the upper floor.	 <p>Narsinghpur नरसिंहपुर Sihi सीही SECTOR 83 शहर 83 Google</p> <p>→ 01 Anup L.C. NISHVAP</p>

Municipal Corporation, Gurugram

Fire Inspection Report : CFC Number 050261923004143



Building : AVL infra pvt Ltd
Reported by : ggnadfo@sr.com

Element	Thursday Oct,31 2019 2:23 PM	Lat = 28.41435618 Long = 76.98000644
Building		 <p>Narsinghpur नरसिंहपुर Sihi सीही SECTOR 53 शुभ 23 Google</p> <p>ON Ramp</p>

Municipal Corporation, Gurugram

Fire Inspection Report : CFC Number 050261923004143



Building : AVL infra pvt Ltd
Reported by : ggnadfo@sr.com

Element	Thursday Oct,31 2019 2:24 PM	Lat = 28.41435618 Long = 76.98000644
Building		 <p>Sihri सीहरी Narsinghpur नरसिंहपुर SECTOR 83 Gurgaon Google</p> <p><i>I.S. Kashyap</i> I.S. KASHYAP A.D.F.O.</p>

Municipal Corporation, Gurugram

Fire Inspection Report : CFC Number 050261923004143

Building : AVL infra pvt Ltd
Reported by : ggnadfo@sr.com



Element	Thursday Oct,31 2019 2:24 PM	Lat = 28.41435618 Long = 76.98000644
Building		 <p>Narsinghpur नरसिंहपुर Sector 83 SECTOR 83 Google OP Dhruv T.S. KASHYAP A.R.P.O.</p>

Municipal Corporation, Gurugram

Fire Inspection Report : CFC Number 050261923004143

Building :
Reported by :



AVL infra pvt Ltd
ggnadfo@sr.com

Element	Thursday Oct,31 2019 2:25 PM	Lat = 28.41435618 Long = 76.98000644
Building		 <p>Narsinghpur नरसिंहपुर</p> <p>Sihi ेशही</p> <p>SECTOR 83 गुरुग्राम</p> <p>Google</p> <p><i>I.S. Kashyap</i></p> <p>I.S. KASHYAP A.D.F.O.</p>

Municipal Corporation, Gurugram

Fire Inspection Report : CFC Number 050261923004143



Building : AVL infra pvt Ltd
Reported by : ggnadfo@sr.com

Element	Thursday Oct,31 2019 2:27 PM	Lat = 28.41435618 Long = 76.98000644
Building		 <p>Narsinghour नरसिंहपुर Sihi सीही SECTOR 83 गुरुग्राम Google</p> <p>→ OR Ame</p>

Municipal Corporation, Gurugram

Fire Inspection Report : CFC Number 050261923004143



Building : AVL infra pvt Ltd
Reported by : ggnadfo@sr.com

Element	Thursday Oct,31 2019 2:28 PM	Lat = 28.41435618 Long = 76.98000644
Building		 <p>Narsinghpur नरसिंहपुर Sihi सीही SECTOR 83 MARKET Google</p> <p>→ OS</p> <p><i>Dune</i></p> <p>I.S. KASHYAP A.D.F.O.</p>

Municipal Corporation, Gurugram

Fire Inspection Report : CFC Number 050261923004143



Building : AVL infra pvt Ltd
Reported by : ggnadfo@sr.com

Element	Thursday Oct,31 2019 2:29 PM	Lat = 28.41435618 Long = 76.98000644
Building		 <p>Narsinghour नरसिंहपुर</p> <p>Siti सीटी</p> <p>SECTOR 83 Block 83</p> <p>Google</p> <p>07</p> <p>Anup</p> <p>INSPECTOR A.D.F.O.</p>

Municipal Corporation, Gurugram

Fire Inspection Report : CFC Number 050261923004143



Building : AVL infra pvt Ltd
Reported by : ggnadfo@sr.com

Element	Thursday Oct,31 2019 2:45 PM	Lat = 28.41353519 Long = 76.979671
Building		 <p>Narsinghpur नरसिंहपुर</p> <p>Sector 51 Block 51</p> <p>Google</p> <p>Handwritten signature: <i>I.S. Kashyap</i></p> <p>I.S. KASHYAP A.D.F.O.</p>

Municipal Corporation, Gurugram

Fire Inspection Report : CFC Number 050261923004143



Building : AVL infra pvt Ltd
Reported by : ggnadfo@sr.com

Element	Thursday Oct,31 2019 2:46 PM	Lat = 28.41353519 Long = 76.979671
Building		 <p>Handwritten notes on the map area: → OU Dheer G.S. ...</p>

Municipal Corporation, Gurugram

Fire Inspection Report : CFC Number 050261923004143



Building : AVL infra pvt Ltd
Reported by : ggnadfo@sr.com

Element	Wednesday Oct,30 2019 4:19 PM	Lat = 28.4148716927 Long = 76.9810670614
Fire Extinguisher		 <p>Narsinghour नरसिंहपुर Sihi सीही SECTOR 83 सेक्टर 83 Google</p> <p>→ /</p> <p><i>Om</i> I.S. KASHYAP A.D.F.O.</p>

Municipal Corporation, Gurugram

Fire Inspection Report : CFC Number 050261923004143



Building : AVL infra pvt Ltd
Reported by : ggnadfo@sr.com

Element	Wednesday Oct,30 2019 4:05 PM	Lat = 28.4144747257 Long = 76.9805467129
Hose Reel		

Municipal Corporation, Gurugram

Fire Inspection Report : CFC Number 050261923004143

Building : AVL infra pvt Ltd
Reported by : ggnadfo@sr.com

Element	Wednesday Oct,30 2019 4:18 PM	Lat = 28.4148716927 Long = 76.9810670614
Down Corner		 <p>Narsinghpur नरसिंहपुर Sihi सीही SECTOR 83 असेक्ट 83 Google</p> <p><i>I.S. Kashyap</i> I.S. KASHYAP A.D.F.O.</p>